Thursday, 11/10/2007 10:12:04 AM

User

Linda Lacelle

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number **Estimate Number**

S.O. No. :

Type

: 35104 : 10804

P.O. Number

This Issue

: 11/10/2007

Prsht Rev. : NC

: // First Issue

Previous Run

Written By

Checked & Approved By

Comment

: 00015

Drawing Name

: D2616-2

Part Number

: D26162 : RTN 649

Drawing Number

Project Number

Drawing Revision

Material **Due Date**

: 18/10/2007

Qty:

2 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: INSPECT WORK TO CURRENT STEP

1.0



Comment: INSPECT RTN 649

2.0

D26162



Mounting Lug



Comment: Qty.:

Mounting Lug

1.0000 Each(s)/Unit

Total:

: MACHINED PARTS

2.0000 Each(s)



3.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



ORIGINAL B/N 'S 1 X B24943 1 X B27886



RE-STAKE BEARING INTO PLACE **4 STAKES ONLY**

TOUCH UP LUGS-GREY, IN STAKED AREAS

XP

4.0

QC5

INSPECT WORK TO CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP

5.0 PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

RE-IDENTIFY USING NEW B/N

Date: < Thursday, 11/10/2007 10:12:04 AM User: Linda Lacelle **Process Sheet** Customer: CC-DAR01 Dart Aerospace Ltd. Drawing Name: D2616-2 Job Number: 35104 Part Number: D26162 Job Number: Seq. #: **Machine Or Operation:** Description: 6.0 FINAL INSPECTION/W/O RELEASE D 00/03 Comment: FINAL INSPECTION/W/O RELEASE 2008/3/12 Job Completion